

# Advantech SE Technical Share Document

<b>Date</b>	2019 / 02 / 18	<b>Related Product</b>	WebAccess/CNC, M2I/CNC	
<b>Category</b>	<input checked="" type="checkbox"/> FAQ <input type="checkbox"/> SOP <input type="checkbox"/> Driver Tech Note			
<b>Abstract</b>	The quick start for NC program edit			
<b>Keyword</b>	WebAccess/CNC, M2I/CNC, Heidenhain iTNC 530 CNC Controller			
<b>Related OS</b>	Windows 7			
Revision History				
Date	Version	Author	Reviewer	Description
2019/02/14	V1.0	JosephSun		

■ **Problem Description & Architecture:**


The document will show you How to create a simple NC program that can run a few minutes (hours) for further application in WebAccess/CNC & M2I/CNC.

■ **Brief Solution - Step by Step:**


**Step1:** Create a new NC program file. (Please add .H filename extension when you create)

-> Select  Programming and Editing key

->  Select/Delet Program & File key


->  NEW FILE key, Please add .H filename extension when you create a new file.


-> To select the unit of measure, press the “MM” key. The TNC switches the screen layout and initiates the dialog for defining the **BLK FORM** as following picture.





**Step2:** Edit NC program with iTNC530 Virtual Keyboard.

-> **WORKING SPINDLE AXIS** Click  key. To confirm Z axis as spindle axis.

-> **DEF BLK FORM: MIN-CORNER** Give a MIN value for X, Y, Z axis with  key.

-> **DEF BLK FORM: MAX-CORNER** Give a MAX value for X, Y, Z axis with  key.



-> **DEF TOOL NUM & CONFIG** Select  key. Give a tool number & Spindle speed value with



key. After that, click



key Ignore the dialog question, until the program-block window display as the following line:

3 TOOL CALL 7 Z S500

-> **MISCELLANEOUS FUNCTION M?** Select



Key. click



key Ignore the dialog question, until

M function can be configure:

4 L M3

-> **LBL SET** Select



Key. click



key until M function can be configure:

5 LBL 1

-> **Dialog / COORDINATES? / FEED RATE F=?** Select



Key. Enter the target coordinate for the X axis,

and go to the next question with



key:

6 L X+100 Y+50 Z+20 F3000

-> **Dialog / COORDINATES? / FEED RATE F=?** Select



Key. Enter the target coordinate for the X axis,

and go to the next question with



key:

7 L X+300 Y+250 Z+60 F1600

-> **LBL CALL** Select




Key to set the times need to repeat of the program with click





key:

8 LBL 1 REP99





### Step3: Save NC program & Run the program.

Select  Switch the soft-key rows key




-> Store the program that you edit.


-> Select  Program Run with Full Sequence key


->  Select/Delet Program & File key

-> Find path: "TNC:\DEMO\AFC\\*.\*" and choose "Adv.H" file (For this example usage) as picture below



-> Click  Machine Functions key

->  NC Start key for running the program that you selected.



■ **Reference:**

Heidenhain iTNC 530 User's Manual HEIDENHAIN