

# UNO Touch Screen Setting Note

2<sup>nd</sup> edition

May 2004

## ***Introduction***


This document introduces how to enable/disable touch screen function.

## ***NOTE***


UNO support the touch screen function of FPM-3120/VOP-1150TV

## ***How to setup the COM port for Touch Screen function***

1. Select "Start"→"Advantech"→"Touch Screen"→"COM Port Config"




- Note that touch screen function will occupy one COM port; therefore, If you want to enable touch screen function, you have to select a COM port for touch screen used.




## How to do Calibration for Touch Screen function


1. Select "Start"→"Advantech"→"Touch Screen"→"Calibration"



2. Touch the end point on the screen to calibrate touch screen function.



3. Press start of task bar of window system and select "**Run**" to execute **regsave**. It will save the settings in the storage device.



4. Restart UNO, then it will apply new touch screen settings that you set.